How do I fix the lean on my 60 Series Land Cruiser?

On the 60 Series Land Cruiser, the rear leaf springs come with a spacer designed to correct any lean. The spacer is initially placed at the bottom of the leaf spring but can be moved to the top to help level the vehicle.

Steps to Correct Lean:

Step 1: Measure the Hub to Guard height on both sides of the vehicle to determine which side is higher.

Step 2: On the higher side, remove the spacer from the bottom of the leaf spring and reposition it on top of the spring to correct the lean.

